



Type code		Displacement $V_1+V_2$ cm <sup>3</sup> /rev	Dimensions						Weight Kg
			A	B	C	D	E	F	
PRD 32-1111 D	PRD 32-1111 S	22.5+4	61	131	171	216.9	15	40	11.8
PRD 32-1112 D	PRD 32-1112 S	22.5+5.5			172.3	219.4	15	40	11.9
PRD 32-1113 D	PRD 32-1113 S	22.5+8			174.4	223.5	20	40	11.9
PRD 32-1114 D	PRD 32-1114 S	22.5+11			178.7	228.5	20	40	12
PRD 32-1116 D	PRD 32-1116 S	22.5+16			178.7	236.9	20	40	12.4
PRD 32-1117 D	PRD 32-1117 S	22.5+19			178.7	242	20	40	12.5
PRD 32-1124 D	PRD 32-1124 S	28+11	63	136	183.5	234	20	40	12.4
PRD 32-1125 D	PRD 32-1125 S	28+14	63	136	185	239	20	40	12.5

# PRD 32

## 1.1.00

Type code		Displacement $V_1+V_2$ cm <sup>3</sup> /rev	Dimensions						Weight Kg
			A	B	C	D	E	F	
PRD 32-1131 D	PRD 32-1131 S	32+4	64.5	139	179.3	225.2	15	40	12.2
PRD 32-1132 D	PRD 32-1132 S	32+5.5			180.6	227.7	15	40	12.2
PRD 32-1133 D	PRD 32-1133 S	32+8			182.7	231.8	20	40	12.3
PRD 32-1134 D	PRD 32-1134 S	32+11			187	236.8	20	40	12.4
PRD 32-1135 D	PRD 32-1135 S	32+14			187	242.5	20	40	12.5
PRD 32-1136 D	PRD 32-1136 S	32+16			187	245.2	20	40	12.6
PRD 32-1138 D	PRD 32-1138 S	32+22.5			190	255	20	40	12.8
PRD 32-1141 D	PRD 32-1141 S	38+4	66.5	145	185	231	15	40	12.5
PRD 32-1142 D	PRD 32-1142 S	38+5.5			186.3	233.4	15	40	12.5
PRD 32-1143 D	PRD 32-1143 S	38+8			188.4	237.5	20	40	12.6
PRD 32-1144 D	PRD 32-1144 S	38+11			192.2	242.5	20	40	12.7
PRD 32-1146 D	PRD 32-1146 S	38+16			192.2	251	20	40	13.1
PRD 32-1151 D	PRD 32-1151 S	45+4	69.5	151	191.5	237.4	15	40	12.4
PRD 32-1152 D	PRD 32-1152 S	45+5.5			192.8	239.9	15	40	12.6
PRD 32-1153 D	PRD 32-1153 S	45+8			195	244	20	40	12.8
PRD 32-1154 D	PRD 32-1154 S	45+11			199	249	20	40	12.9
PRD 32-1156 D	PRD 32-1156 S	45+16			199	257.4	20	40	13.3
PRD 32-1167 D	PRD 32-1167 S	56+19	77	162	210	274	20	40	14.5
PRD 32-1187 D	PRD 32-1187 S	70+19	87.2	173	221	285	20	40	